

FITNESS CERTIFICATE

(TO BE FILLED BY THE INSPECTING OFFICER)

1. Name of Officer : Nizam. I
2. Name of the School : Marthoman Vidyapeedom
3. Location : Niranam, Thiruvalla
4. Classification of building as specified in : certificate and size
4 column of the application for fitness
5. Period for which the certificate is issued : 2025-26
6. Nature of defect, if any :
 - a. Foundation and basement
 - b. Superstructure
 - c. Doors and windows
 - d. Wood work wrought and put up
 - e. Roof
 - f. Flooring
 - g. (Miscellaneous (cracks))Nil
7. Any major defect noted which will make the Building unsafe in any manner : No
8. Whether maintenance work have been Properly done : Yes
9. Whether the structure is sound or not conducting : Sound under normal weather
classes Conditions

Note: 1. The stability of the structure should be examined with reference to location altitude of wing exposure to flood etc.

2. Any additional observation if deemed necessary for the certificate

CERTIFICATE

Certified that the school was inspected by me on 30/05/2025 and found to be fit to conduct classes from the period of academic year 2025-26 for the reasons stated above.

Place: Niranam
Date: 30/05/2025



[Handwritten Signature]

ASSISTANT ENGINEER
L.S.G.D. (Public Works) Section
Niranam, Pulikeezhu Block

MANAGER
Marthoman Vidyapeedom
Public School
Niranam P.O.
Thiruvalla-689 652

**APPLICATION FOR FITNESS CERTIFICATE OF SCHOOL FITNESS
(TO BE FILLED IN BY THE SUPERVISOR)**

1. Name of School : MARTHOMAN VIDYAPEEDOM
2. Location with name of Block : PATHANAMTHITTA, NIRANAM,
THIRUVALLA.
2024-25
30.05.2024
Assistant Engineer
Niranam, Pulikeezhu
Multi storeyed
3. Whether Fitness certificate has been Issued in previous year and if so the No. and date of the last certificate and the authority who issued it :
30.05.2024
Assistant Engineer
Niranam, Pulikeezhu
Multi storeyed
4. Classification of the building size :
(Basis for classification see Anneture-1)
i. Permanent single or multi storeyed : Permanent
19.00 x 8.50
19.00 x 8.50
04.45 x 6.75
21.45 x 8.5
In 3 floors total 1606 M
5. Year of constitution of different building: 2013-14
6. Short specification. Score of the Specification not applicable : Details attached
concrete, steel
7. i. Foundation and basement (Rubble in: Lime mortar/cement mortar/mud mortar) : concrete, steel, bricks
ii. Superstructure (Rubble in lime cement mud or brick state in lime cement for pillar's with intermediate walls with sundried bricks)
iii. Doors and windows country wood : Concrete frame
(mention species) Steel frame
iv. Wood work wrought and put up country wood mention species wrought and full or half bamboo for drafters/iron trusses Wood for doors
Glass for windows
v. Kind of roof with short specification of materials used R.C.C/Taded/Thatched/ A.C.Sheets : RCC
vi. Flooring : Half hand broken tiles and half
Cement plastered over/hand broken/ concrete
stone
Concretes building/gravel concretes
Gravel beded laterite chips or cow dung washed
vii. Whether regular maintenance attended : attended, every year
to or not period during which last maintenance was done

I Abraham Varghese solemnly declare that the above details furnished are correct to the best of my knowledge.

Place : Niranam
Date: 30.05.2025



Signature

MANAGER
Marthoman Vidyapeedom
Public School
Niranam P.O.
Thiruvalla-689 621